



Paslode[®]
Impulse

IM90i





1



= 1250
(-5 °C)

Paslode
Impulse





3




= 4000

Paslode
Impulse






2



Paslode
Impulse



Ø. 2.5 ▶ 3.1 mm
L 50 ▶ 90 mm
RoundDrive®






















4

- 15 °C ▶ + 49 °C

2-3/s
1000/h
4000/day









RESET













Bzzzzzz !






~~Bzzzzzz !~~



Bzzzzzz !





115251

